



Model	$L_H$ A	$L_T$ A	$V_{max}$ V	$I_{max}$ A	$P_{dmax}$ W	$R_{min}$ $\Omega$	$R_{max}$ $\Omega$	A (max)	B (max)	C (typ)	D (min)
T30-090	0.90	1.80	30	40	0.61	0.07	0.13	7.6	12.4	5.1	7.6
T30-110	1.10	2.20	30	40	0.71	0.05	0.10	7.6	14.4	5.1	7.6
T30-135	1.35	2.70	30	40	0.82	0.04	0.08	9.1	13.7	5.1	7.6
T30-160	1.60	3.20	30	40	0.91	0.03	0.07	9.1	15.4	5.1	7.6
T30-185	1.85	3.70	30	40	1.00	0.03	0.06	10.4	15.9	5.1	7.6
T30-250	2.50	5.00	30	40	1.21	0.02	0.05	11.6	18.5	5.1	7.6
T30-300	3.00	6.00	30	40	2.01	0.02	0.05	11.6	17.5	5.1	7.6
T30-400	4.00	8.00	30	40	2.52	0.01	0.04	14.2	20.3	5.1	7.6
T30-500	5.00	10.00	30	140	3.01	0.01	0.03	14.2	25.1	10.2	7.6
T30-600	6.00	12.00	30	40	3.51	0.005	0.02	16.7	25.1	10.2	7.6
T30-700	7.00	14.00	30	40	3.80	0.005	0.02	19.3	26.9	10.2	7.6
T30-800	8.00	16.00	30	40	4.00	0.005	0.02	21.8	29.4	10.2	7.6
T30-900	9.00	18.00	30	40	4.21	0.005	0.01	24.3	29.9	10.2	7.6