



sensor1	Receive	Red cable
sensor2	Transmit	Glue Cable
sensor3	Receive	Black Axial (Black, Blue cable)
sensor4	Receive	Black Axial (Red, White cable)
sensor5	Transmit	Red cable
sensor6	Receive	Glue Cable
sensor7	Transmit	Black Axial (Black, Blue cable)
sensor8	Transmit	Black Axial (Red, White cable)



Unmarked Tolerance		mark	Content of Amendment	Edition	Author	Date
from (mm)	to (mm)	Quality Level				
0	10	±0.05				
10	50	±0.10				
50	100	±0.15				
100	200	±0.20				

mark	Content of Amendment	Edition	Author	Date
Design		standard		
Drawing		process		
Check		Approve		

SAW screen specs			
sign	weight	Scale	
A0		Free	
Total X 1 P X 1 P			


product
 CTB420C-4K
 Drawing No.